


#4534 BondingTrays: Support for Printing

To ease 3D printing of virtually planned bracket transfer trays (e.g. on 3D printer [Asiga MAX](#)), since build 3.2.90 (209) a new design option [Contact Surface] is available in control panel [Tray] in module [BondingTrays](#):



From:
<http://onyxwiki.net/> - [OnyxCeph³™ Wiki]

Permanent link:
<http://onyxwiki.net/doku.php?id=en:4534>

Last update: 2017/10/22 12:49

