


Module Cast Adjust

First Steps

1. Activate "Clipping (Line)" in tab "Clip Object"
2. Place Landmarks at the model border, last point close to the first one
3. Press button "Trim" and confirm the correct trimming
4. Select and add socket in tab "Model Base"
5. Save as new finding

Module user interface



References

Screenshots	
3D Views	
Videos	youtube Google
Links	

From:

<http://onyxwiki.net/> - [OnyxCeph3™ Wiki]

Permanent link:

http://onyxwiki.net/doku.php?id=en:base_tray&rev=1584625249

Last update:

2020/03/19 14:40

